


Plainwell No. 2 Dam Area 2013 Bank Monitoring

September 23, 2013

Agenda

- Introduction
- Status of 2013 BCMR
- Erosion Identified in 2013
- Bank Maintenance Options
- Proposed Bank Maintenance Plan
- Path Forward

Erosion Identified in 2013




Transect T-15 – Removal Area 2





LEGEND:

- FINISHED GRADE/RESTORATION SURFACE
- 2013 SURVEYED GRADE
- WATER ELEVATION AT TIME OF SURVEY
- MEDIAN WATER ELEVATION (APPROX.)



Transect T-16 – Removal Area 3A




Transect T-17 – Removal Area 4A



LEGEND:

- FINISHED GRADE/RESTORATION SURFACE
- 2013 SURVEYED GRADE
- WATER ELAVATION AT TIME OF SURVEY
- - - MEDIAN WATER ELEVATION (APPROX.)




Transect T-18 – Removal Area 4B




LEGEND:

- FINISHED GRADE/RESTORATION SURFACE
- 2013 SURVEYED GRADE
- WATER ELEVATION AT TIME OF SURVEY
- MEDIAN WATER ELEVATION (APPROX.)



T-18


Proposed 2013 Bank Maintenance Areas



Possible Bank Maintenance Options

- Armor Stone
- Coir Log
- Woody Vegetation
- Woody Debris
- Other

Woody Debris



Woody Debris



Proposed 2013 Bank Maintenance

- RA 2, 3A and 4A
 - Woody Debris (Fall 2013)
 - Willow live plants (Spring 2014)

Path Forward

- Agency comments on 2013 BCMR
- Agency approval of conceptual bank maintenance plan
- Georgia-Pacific to provide Tech Memo describing bank maintenance plan
- Agency approval of Tech Memo
- Georgia-Pacific to schedule and perform bank maintenance